

Rose-Hulman Institute of Technology

Rose-Hulman Scholar

Faculty Publications - Civil Engineering

Civil Engineering

Spring 5-2021

How Structural Engineers Find Errors in Analysis and Design Results. Practice Periodical on Structural Design and Construction

James Hanson

Follow this and additional works at: https://scholar.rose-hulman.edu/civil_fac



Part of the [Civil Engineering Commons](#)

1 **How Structural Engineers Find Errors in Analysis and Design**

2 **Results**

3 James H. Hanson, P.E., Ph.D., M.ASCE¹

4 [This is a final draft version. The published paper is available at

5 <https://ascelibrary.org/doi/10.1061/%28ASCE%29SC.1943-5576.0000560>]

6
7 **Abstract:** Errors in structural analysis and design are inevitable, but finding them early in the
8 design process saves time and money. Knowledge of the broad causes of errors and how
9 experienced engineers identify the presence of errors can inform training for structural engineers
10 thus empowering them to find their own errors early in the design process. Therefore, this study
11 presents 145 pieces of information about errors in structural analysis and design compiled from
12 structured interviews with 35 structural engineers. The strategies used to find errors have been
13 classified into eight categories: Comparison, Rule of Thumb, Information Check, Visualization,
14 Extreme Value, Previous Experience, Field, and Other. Evaluation of the information shows that
15 responsibility for quality control should not be held only with reviewers but should also be shared
16 with the engineers creating the designs. Also, quality control training should be heavily influenced
17 by the Comparison strategies. Overall, the specific examples of errors and the problems they cause
18 could be helpful in developing in-house training and updating quality control procedures.

19
20 **Author keywords:** Analysis; Design; Errors; Mistakes; Quality Control.

21

¹ Professor, Civil & Environmental Engineering, Rose-Hulman Institute of Technology, Terre Haute, IN 47803. E-mail: james.hanson@rose-hulman.edu

22

23

24

25

26 **Motivation**

27

28 Today's competition in the marketplace and complexity of structural designs necessitate the use
29 of computers for structural analysis and design. With the introduction of computers, however,
30 came the ability to make errors faster than ever before (Huston 2007, Weingardt 2013, Ruby 2020).

31 For the purposes of this paper, "error" is defined as any act or omission by the engineer that would
32 cause the design to not perform as intended. Errors in structural engineering are inevitable. The
33 key is when the errors are found. Stecklein *et al.* (2004), studied the cost of finding errors at
34 different stages of a project's life cycle. They were studying the development of hardware-
35 software systems for NASA-type projects. Consistent with researchers in other fields, they found
36 an exponential growth of cost of errors as a project proceeds through development. Their study
37 showed that the cost of finding an error during operations, the structural engineering equivalent of
38 finding it in the field, resulted in more than a 50× increase in cost to fix the error compared with
39 finding the error during design.

40 The cost of finding structural engineering design errors in the field is also significant.
41 Peansupap and Ly (2015) studied 11 building projects in Cambodia in order to determine the
42 impact of design errors. They asked a civil engineer on each project to evaluate the likely impact
43 of 122 different errors on the cost and schedule for the project. The errors on the list had all been
44 observed previously by the engineers. For six of the projects, the likely impact would be "severe"

45 where severe was defined as resulting in design revision, additional cost, but not a delay in the
46 construction process. Lopez and Love (2012) obtained estimates of construction costs incurred
47 due to design errors for 139 projects in Australia. The mean total cost of fixing the error was
48 14.3% of the original project price considering both direct and indirect costs.

49 Fast-tracking projects, starting construction before the design is complete, is becoming
50 common. In 2002 Knecht reported that fast-track construction accounted for up to 40% of building
51 projects at that time. Indications are that the percentage has increased since then. The faster time
52 to construction means errors must be found earlier in the design process to avoid being found in
53 the field. Also, in the typical building design process the structural engineer is making design
54 decisions well in advance of the other design professionals (e.g., mechanical, electrical, plumbing);
55 therefore, errors in the structural design must be found early to avoid a ripple effect of changes.

56 Finding errors in structural engineering designs as early as possible in the project life cycle
57 will result in the smallest financial and time impact on the project. How structural engineers find
58 those errors has not been well documented though. Authors have shared their personal
59 recommendations (e.g., Ioannides *et al.* 2000, Willard and Quinn 2010a-d), but there has not been
60 a broad study of the errors made, the problems caused by those errors, or the skills used to identify
61 that there is an error. Knowledge of the broad causes of errors and how experienced engineers
62 identify the presence of errors can inform training for structural engineers thus empowering them
63 to find their own errors early in the design process.

64

65

66

67

68 **Interview Process**

69

70 To discover how structural engineers identify the presence of an error, interviews were conducted
71 with building designers with a broad range of experiences. In total, 35 engineers from 9 different
72 firms were interviewed during the second half of 2004. The participating firms were located in
73 seven different states: New York, Pennsylvania, Indiana, Illinois, Texas, California, and Hawaii.
74 The specific offices of those firms ranged in size from 1 to 55 structural engineers. Five of the
75 engineers were female. The experience level of the engineers ranged from 1 to 55 years, with a
76 median of 8 years. All but six of the engineers had their P.E. license at the time of the interviews.
77 The highest degrees of the engineers were the following: 8 Bachelors, 26 Masters, and 1 Doctorate.

78 Several approaches were used to elicit information from the engineers in the interviews: the
79 critical incident technique, question-and-answer, and a case study. The critical incident technique
80 uses prompts to help subjects recall past events in detail. The following two prompts were used
81 to elicit experiences from the engineers:

82 “Think of the *most recent* time you discovered something unreasonable in the results of
83 analysis or design.”

84 “Think of the *most alarming* discovery you have made of something unreasonable in the results
85 of analysis or design.”

86 Detailed information on how to implement the critical incident technique is provided in other
87 resources (Flanagan 1954; Hanson and Brophy 2012). In the question-and-answer part of the
88 interview, the engineers were asked “What are common errors you have seen?” Follow-on
89 questions often included probes such as “How do you check for those errors?” Four of the firms
90 also participated in a case study. They were given the floor plans for a small building and asked

91 to perform preliminary design. The engineer who was assigned the case study spent between 10
92 and 40 hours on the design. In the interview, the case study was used as a catalyst for discussion
93 about how the engineer evaluated the reasonableness of results.

94 It is important to note that the interviews were not structured to gather statistics on errors, so it
95 would be inappropriate to conclude that the distribution of types of errors or how they are found
96 reflects the distribution in day-to-day practice. The interviews were structured, however, to gather
97 as many examples as possible of errors and how to find them.

98

99

100 **Summary of Interview Results**

101

102 After reviewing the information from the 35 interviews using the three approaches, the various
103 ways practitioners find errors were grouped into eight categories:

104 *Comparison.* This category involves comparing calculation results from two or more
105 approaches or situations (e.g., hand calculations versus computer results, results from two
106 different computer programs, results considering different conditions, results from two
107 different engineers).

108 *Rule of Thumb.* This category involves use of empirically-based formulas to predict member
109 sizes or properties.

110 *Information Check.* These approaches are about review of information and process without
111 using calculations. They include verifying the codes used and steps followed.

112 *Visualization.* This refers to visualizing the load path. Typically it involves making cuts and
113 confirming that forces have a continuous path to the foundation.

114 *Extreme Value.* In some cases, the solution obtained is ridiculously large or small, thereby
115 making it obviously incorrect.

116 *Previous Experience.* These strategies can only be developed through experience. They
117 typically involve recognizing a situation as similar to previous projects.

118 *Field.* This is the least preferred strategy. It means that the problem is discovered during or
119 after construction.

120 *Other.* This category includes all of the other strategies used to discover a problem.

121

122 The three interview approaches revealed 73 specific instances where an error was discovered.
123 Much of the data provides information on the type of error and how it was found. Of the 73
124 instances, only twice did an engineer remember the error but not how it was discovered. In the
125 question-and-answer part of the interview, the engineers identified 35 additional approaches to
126 finding errors. The engineers were also able to identify 37 common errors even though they did
127 not provide information on how they would find those errors. By comparing these common errors
128 with the specific examples, the author was able to annotate each common error with the category
129 of strategy that would likely allow an engineer to identify the common error. Table 1 tallies the
130 occurrences of each category of tool, and the Appendix contains the detailed results.

131 The results show that Comparison was the strategy used most broadly to identify errors.
132 Previous Experience was also a commonly used strategy, but those experiences must be developed
133 over time. Comparison, Rule of Thumb, Information Check, Visualization, and Extreme Value
134 are all strategies that can be learned, and they accounted for more than half of the strategies
135 identified by the engineers. The Other category contains mostly procedural checks but also some
136 unique experiences; therefore, the specific examples in this category might be used to inform

137 quality control checklists. There were very few errors that were repeated by different engineers,
138 so the results list a broad range of structural engineering errors. The most commonly mentioned
139 error was “Changes in layout not articulated by architect or not noticed by structural engineer.”
140 That error was identified by three engineers each from a different firm. In follow-up conversations,
141 multiple structural engineers stated that Building Information Modeling (BIM) has not fixed this
142 problem.

143 For the specific instances recalled in the study, the engineers identified whether they found the
144 error in their own work or in another engineer’s work. Table 2 shows this breakout by category
145 of tool. A significant percentage of errors was found by each; therefore, quality control checks are
146 effectively used by both the engineers doing the work and engineers reviewing other’s work. For
147 the instances reported, Comparison was by far the most often used strategy when finding errors in
148 their own work. Previous Experience was the most often used when finding errors in other’s work.
149 This might be due, at least in part, to the tendency of reviewers to have more experience. The
150 other commonly used strategies to find errors in other engineer’s work were Rule of Thumb,
151 Comparison, and Information Check.

152 Finding structural engineering errors in the field is the least desirable approach. Reviewing
153 the details of the 13 instances where the error was found in the field and comparing them with the
154 eight categories of tools, potential categories of tools have been assigned that might have caught
155 the errors before construction in the field (Table 3). In two of the instances, the engineer was not
156 certain whether the error was made on the engineering side or the construction side; therefore, no
157 categories were identified for those two instances. For seven of the instances, Information Checks
158 might have caught the error; therefore, some of the errors identified in the study could have been
159 found before construction. For four of the instances, however, the error would most likely have

160 been found only by Previous Experience or Other strategies. Since these strategies are the most
161 dependent on the specific experiences of the engineer reviewing the work, these four errors were
162 the most likely to go undetected until the field. Therefore, enhanced training on quality control
163 strategies might not eliminate errors getting to the field but could reduce them. Table 4 contains
164 additional information on how the errors in the field were detected.

165

166

167 **Conclusions**

168

169 Interviews with 35 practicing structural engineers resulted in 145 pieces of information about
170 errors in structural analysis and design. Over one hundred of those included strategies for how to
171 find the error. From the results of this study, we can draw the following conclusions:

- 172 • Responsibility for quality control should not be entirely delegated to reviewers but should
173 be encouraged of the structural engineers performing the work. There are proven strategies
174 for finding errors in one's own work, so it can be done. The earlier errors are found the
175 smaller the cost in time and money, so it should be done.
- 176 • The most broadly used category of strategies for finding errors is Comparison; therefore,
177 quality control training for structural engineers should be heavily influenced by
178 Comparison strategies.
- 179 • Other than Previous Experience, the most broadly used categories by engineers to find
180 errors in another person's work are Comparison, Rule of Thumb, and Information Check.
181 These can be taught, so there is opportunity train engineers on how to use these strategies
182 to find errors in their own work.

- 183 • Previous Experience is the most broadly used category by engineers to find errors in
184 another person’s work. One option is to develop that experience slowly over time.
185 However, studying common errors and the problems they cause might help junior
186 engineers develop experience-based error identification skills faster. The broad list
187 contained in the Appendix can be used for such a purpose.
- 188 • Some errors currently being found in the field could reasonably be found sooner. Some
189 errors will likely continue to be found in the field, but reducing that number would have
190 significant financial benefits. Reducing the number of errors found in the field would also
191 potentially avoid harm to a firm’s reputation.

192

193 The increasing use of computers and increasing pace of design mean greater risk of structural
194 engineering errors going undetected until construction in the field. Conversely, finding errors as
195 early as possible significantly reduces the impact in terms of cost and time. Understanding how
196 experienced structural engineers find errors could help inform training and quality control
197 procedures so that more errors are identified by the engineer doing the work, thus earlier in the
198 design process.

199

200

201 **Appendix – Additional Information from Interviews**

202

203 Table 4 presents the information gathered about all 73 instances where the engineer recalled a
204 specific error. The columns include what was not reasonable, “The Problem”; what happened to
205 bring about the problem, “The Error”; how someone knew there was a problem, “The Tool for

206 Evaluating”; and whether the error was found in the interviewee’s work or someone else’s work.
207 The category of tool was assigned as part of this study.

208 Table 5 presents an additional 35 approaches to finding errors, labeled as “The Tool for
209 Evaluating”. In most cases, the engineer was able to link that tool to common causes, “The Error”,
210 and in some cases the engineer was able to identify a common effect of the error, “The Problem”.
211 The category of tool was assigned as part of this study. Although not common, duplicate entries
212 from different engineers are presented to reflect how widespread some evaluation tools are used.

213 Table 6 presents 37 common errors and the resulting problems. Duplicate entries from
214 different engineers are presented as evidence of how common some errors are.

215

216

217 **Data Availability Statement**

218

219 All data, models, and code generated or used during the study appear in the submitted article.

220

221

222 **Acknowledgements**

223

224 This study was made possible by the National Science Foundation, grant no. DUE-0341212. The
225 author would like to thank the many engineers who participated in the interviews from the
226 following firms: Applied Technology Corporation; Arup; Burns Engineering; Leslie E. Robertson
227 Associates, R.L.L.P.; McComas Engineering, Inc.; MMS-A/E; Skidmore, Owings & Merrill LLP;
228 Spencer Engineering, Inc.; Thorton-Thomasetti Group; and Walter P. Moore and Associates, Inc.

229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251

References

Flanagan, J. C., 1954, "The Critical Incident Technique," *Psychological Bulletin*, Vol. 51, No. 4, July, pp. 327-358.

Hanson, J. H., and Brophy, P. D., 2012, "The Critical Incident Technique: An Effective Tool for Gathering Experience From Practicing Engineers", *Advances in Engineering Education*, American Society for Engineering Education, Vol. 3, Iss. 1.

Huston, E. T., 2007, "Are We Relying Too Much on Computers?", *Structure Magazine*, Joint publication of the National Council of Structural Engineers Associations (NCSEA), ASCE's Structural Engineering Institute (SEI), and the Council of American Structural Engineers (CASE); Vol. 14, No. 2, February, pp. 7.

Ioannides, S. A., and Ruddy, J. L., 2000, "Rules of Thumb for Steel Design," *Modern Steel Construction*, American Institute of Steel Construction; Vol. 40, No. 2, February.

Knecht, B., 2002, "Fast-Track Construction Becomes the Norm," *Architectural Record*, Vol. 190, Iss. 2, p. 123.

Lopez, R. and Love, P. E. D., 2012, "Design Error Costs in Construction Projects," *Journal of Construction Engineering Management*, American Society of Civil Engineers, Vol. 138, No. 5, May, pp. 585-593.

Peansupap, V. and Rothmony, L., 2015, "Evaluating the Impact Level of Design Errors in Structural and Other Building Components in Building Construction Projects in Cambodia," *Procedia Engineering*, Elsevier, Creative Construction Conference, Vol. 123, pp. 370-378.

252 Ruby, D., 2020, "Coordination and Completeness in a BIM Dominated World," *Structure*
253 *Magazine*, Joint publication of the National Council of Structural Engineers Associations
254 (NCSEA), ASCE's Structural Engineering Institute (SEI), and the Council of American
255 Structural Engineers (CASE); Vol. 27, No. 6, June, pp. 38-40.

256 Stecklein, J. M., Dabney, J., Dick, B., Haskins, B., Lovell, R., and Moroney, G., 2004, "Error Cost
257 Escalation Through the Project Life Cycle," Conference Paper, National Aeronautics and
258 Space Administration, Report JSC-CN-8435.

259 Weingardt, R. G., 2013, "Heighten Your Intuitiveness," *Structural Engineer*, Zweig Group;
260 March, pp. 50.

261 Willard, L. and Quinn, B., 2010a, "Reducing Your Risk in Using Structural Software: Educating
262 Your Engineers," *Structural Engineering & Design*, Vol. 11, No. 2, March, pp. 16.

263 Willard, L. and Quinn, B., 2010b, "Reducing Your Risk in Using Structural Software: Written
264 Processes and Procedures," *Structural Engineering & Design*, Vol. 11, No. 2, March, pp. 16.

265 Willard, L. and Quinn, B., 2010c, "Reducing Your Risk in Using Structural Software: Verification
266 of Results," *Structural Engineering & Design*, Vol. 11, No. 6, July, pp. 16.

267 Willard, L. and Quinn, B., 2010d, "Reducing Your Risk in Using Structural Software: Perform
268 Internal Reviews of Models," *Structural Engineering & Design*, Vol. 11, No. 10, November,
269 pp. 16.

270

271

272

273

274 **Table 1.** Summary of results of interviews categorized by the type of tool used to identify the
 275 error.

276

Category of Tool	Identified Incidents	Identified Additional Approaches	Described Common Problems
Comparison	15	19	12
Rule of Thumb	7	0	0
Information Check	6	3	7
Visualization	3	2	0
Extreme Value	3	1	0
Previous Experience	20	5	7
Other	4	4	11
Field	13	1	0
Not Reported	2		
Total	73	35	37

277

278

279

280

281 **Table 2.** Breakout of who’s work contained the error for the specific instances identified in the
 282 interviews.

283

Category of Tool	Found in Own Work	Found in Other's Work
Comparison	10	5
Rule of Thumb	1	6
Information Check	1	5
Visualization	1	2
Extreme Value	1	2
Previous Experience	4	16
Other	1	3
Field	9	4
Not Reported	1	1

284

285 **Table 3.** Potential categories of error detection strategies that might have been used to find errors
 286 before construction in the field.

287

What was unreasonable [The Problem]	What happened to bring about the problem [The Error]	Potential Category of Tool
Insufficient information on the drawings	Failed to check the drawings	I or O

Assumptions about structural performance were invalid	Followed standard practice, but that was not applicable in this case	P or O
Applied a design procedure outside its range of applicability	Did not realize that it was outside the range of applicability	I or O
Member underdesigned	Error in labeling beam size on drawing	I or P
Discontinuity of longitudinal reinforcement in a beam	Supporting wall was removed from the plan, but a beam detail was not updated	I or O
Inadequate strength across a construction joint	Did not anticipate that the construction joint would be placed in high stress zone	I or O
Member extended below the ceiling	Chose beam size to continue the adjacent beam's depth	P or O
Member too small	Did not consider all loading conditions; did not consider deflection performance	I or O
Steel member too short	Unknown	-
Member underdesigned	Failed to recognize P-delta effects	P or O
Software used for a situation not intended	Company began new a construction method but used software for an old construction method	I or O
Excessive deflection of slab	Contractor did not recognize that walls under the slab would be bearing walls	-
Deformation of structure under self-weight interfered with erection	Engineer did not consider this effect in the design or specifications	P or O

288

289 **Note:**

290 *Categories of Tools*

291 I = Information Check (no calculations)

292 O = Other

293 P = Previous Experience

294

295 **Table 4.** Specific instances where an error in analysis or design was identified.

296

What was unreasonable [The Problem]	What happened to bring about the problem [The Error]	How to know there was a problem [Tool for Evaluating]	Category of Tool	Own Work/ Other's Work
Slab underdesigned	Assumed rigid diaphragm in 3D analysis, so did not "see" the magnitude of forces in the slab	Calculated forces in the slab as a check	C	Own
Incorrectly combined most extreme loading location and most extreme loading magnitude, but both cannot happen at the same time	Lack of information provided by the manufacturer	Calculations indicated that a design functioning adequately should have failed in the field	C	Other
Member oversized	Error in in-house software	Changing input values had little effect on results, even when checked extreme values	C	Own
Members underdesigned	Understanding of boundary conditions changed	Checked members with revised boundary conditions	C	Own
Members oversized		Compared beam sizes from one floor to another in the	C	Other

		same structure at the same location		
Incorrect building response	Incorrectly modeled the idealized structure	Compared the period of vibration to similar structures (previous experience)	C	Own
Incorrect building response	Forgot to include some live loads on mechanical floors in the computer model	Compared the weight of the building with the total axial load calculated by computer	C	Own
Underestimate axial force in beam	Analysis performed in 3D with a rigid diaphragm which slaves the nodes, so no axial forces were produced	Compared with an analysis without a rigid diaphragm	C	Own
Incorrect distribution of moments to members at a rigid connection	Incorrectly modeled the idealized structure	Computer results did not match hand results	C	Own
Incorrect building response	Fixed node at the top of the structure	Deflected shape was not what was expected	C	Own
Spreadsheet used a fixed value even though there was a cell for inputting the value	Limitation of software	Member strength was unchanged when dimensions were changed	C	Own
Members underdesigned	Did not properly determine internal forces accounting for	Redesigned under new code	C	Other

dynamic effects; failed
to scale the results from
static analysis

Members under- or overdesigned	Calculation errors by designer	Two different structural alternatives produced nearly identical member sizes	C	Other
Members under- or overdesigned	Load placed in incorrect location in the computer model	Two similar loading situations produced very different results	C	Other
Member overdesigned	Used design software to design members outside the range anticipated by the software	Unable to design a member to have adequate capacity	C	Own
Insufficient information on the drawings	Failed to check the drawings	Beam was constructed through a stairwell at chest height	F	Own
Assumptions about structural performance were invalid	Followed standard practice, but that was not applicable in this case	Cracks formed in a slab on grade that was post- tensioned to avoid cracks	F	Own
Applied a design procedure outside its range of applicability	Did not realize it was outside the range of applicability	Excessive cracking developed in a concrete member in field	F	Own
Member underdesigned	Error in labeling beam size on drawing	Excessive deflection observed during erection	F	Other

Discontinuity of longitudinal reinforcement in a beam	Supporting wall was removed from the plan, but a beam detail was not updated	Identified in a field inspection during construction	F	Other
Inadequate strength across a construction joint	Did not anticipate that the construction joint would be placed in high stress zone	Identified in a field inspection during construction	F	Own
Member extended below the ceiling	Chose the size to continue adjacent beam depth	Identified after constructed	F	Own
Member too small	Did not consider all loading conditions; did not consider deflection performance	Member behaved poorly in the field; too flexible	F	Own
Steel member too short	Unknown	Member did not fit properly in the field	F	Own
Member underdesigned	Failed to recognize P-delta effects	Member failed during construction	F	Other
Software used for a situation not intended	Company began new a construction method but used software for an old construction method	Member failed during construction	F	Other
Excessive deflection of slab	Contractor did not recognize that walls under the slab would be bearing walls	Observed in field while casting slab	F	Own

Deformation of structure under self-weight interfered with erection	Engineer did not consider this effect in the design or specifications	Pieces did not fit in the field	F	Own
Deflections out of allowable tolerance	Not considered by the manufacturer	Deflections were not indicated on the shop drawings	I	Other
Connection drawn incorrectly	Change not updated on the drawings	Designer identified it while proofing drawings	I	Own
Insufficient details drawn	Failed to recognize that a single detail was being referenced for multiple, different conditions	Identified it while reviewing design drawings for sufficient information	I	Other
Member underdesigned	Failed to factor load	Reviewed the design procedure	I	Other
	Took a wrong coefficient from the code	Second engineer checked the criterion	I	Other
	Failed to recognize that there were rooftop units when calculated loads on roof	Second engineer checked the design criteria with the problem statement	I	Other
Inappropriate loads used for design	Lack of understanding of how to use the pertinent codes		NR	Other
Parking garage slab was too thin	Designed the thickness to provide sufficient		NR	Own

slope for runoff, but
 didn't check the required
 minimum thickness

Larger column above a smaller column	Used computer to pick most efficient sections	Checked for uniformity of column size at different levels	O	Other
Members underdesigned	Effect of extremely stiff transfer girder was not considered in the lateral response of a concrete rigid frame	Checked for this in a design review	O	Other
Foundation underdesigned	Forgot the self-weight of the structure	Remembered later	O	Own
Snow load used for design was less than the required value	Did not recognize drifting effect	Structural failures in the region motivated a closer look at the loads	O	Other
Member underdesigned	Rushing to get drawings out, failed to revise the final member size	Experience showed that a combined loading member should be governed by axial load, but the section chosen was governed by bending	P	Other
Selection of member sizes was inefficient	Failed to recognize that increasing the stiffness of other members would reduce internal forces in the overloaded member	Recognized that members were out of scale compared with previous experience	P	Other

Member underdesigned	Computer design was based on the assumption of a braced top flange, but was not true in this case	Minimum size for perimeter beams that brace façade panels should have been W14x22 based on previous experience	P	Other
Member not sufficiently stiff for serviceability	Did not check service behavior, only strength	Non-standard detail was identified based on previous experience	P	Other
Beam flange of a composite beam not thick enough to weld studs	Designed by computer for strength	Identified based on previous experience	P	Other
Beam size too small to allow bolted connection to girder	Designed by computer for strength	Identified based on previous experience	P	Other
Beam-column connections were not designed to carry the restraining force to prevent column buckling	Failed to consider the load condition	Identified based on previous experience	P	Other
Concrete member was not detailed in accordance with code requirements	Inexperience	Identified based on previous experience	P	Other
Detail was not appropriate	Copied from previous design without verifying that detail was valid for the current situation	Identified based on previous experience	P	Other
Joist spacing too wide	Flaw in computer design software	Identified based on previous experience	P	Own

Ledger beam underdesigned	Unknown	Identified based on previous experience	P	Other
Member underdesigned	Took results directly from computer program	Identified based on previous experience	P	Other
Member underdesigned	Unknown	Identified based on previous experience	P	Other
Members underdesigned	Error made when determining wind loads	Identified based on previous experience	P	Other
Reinforcement on wrong side of concrete member	Unknown	Identified based on previous experience	P	Other
Required splice was not detailed	Did not recognize that a timber member could not be supplied in the length prescribed	Identified based on previous experience	P	Other
Steel connection was not designed to account for all loads	Failed to consider connection eccentricity	Identified based on previous experience	P	Other
Connection not properly designed	Failed to consider all possible failure modes	Identified based on previous experience of reviewer	P	Own
Foundation underdesigned	Missed some loads from the architect's drawings	Identified based on previous experience of reviewer	P	Own
Steel connection was not designed to minimum code requirements	Inexperience	Identified based on previous experience of reviewer	P	Own
Steel beam overdesigned	Double counted beam self-weight in computer design	Checked reactions at the end of member and compared them to hand calcs; used a	R	Own

rule of thumb for depth:
depth in inches at least 1/2
the span in feet

Member underdesigned	Unknown	Used a rule of thumb for cantilevered steel beams: depth in inches at least the span in feet	R	Other
Member not sufficiently stiff for serviceability	Designed by computer for strength	Used a rule of thumb for steel beams: depth in inches at least 1/2 the span in feet	R	Other
Member not sufficiently stiff for serviceability	Designed for strength and limited by ceiling height, but not checked for serviceability	Used a rule of thumb for steel beams: depth in inches at least 1/2 the span in feet	R	Other
Member underdesigned	Misinterpreted the units in the design tables	Used a rule of thumb for steel beams: depth in inches at least 1/2 the span in feet	R	Other
Members overdesigned	Designer did not account for composite action	Used a rule of thumb for steel beams: depth in inches at least 1/2 the span in feet	R	Other
Steel beam was too shallow for the span	Computer designed for strength, not serviceability	Used a rule of thumb for steel beams: depth in inches at least 1/2 the span in feet	R	Other
Discontinuity in load path	Engineer initially missed part of the load path	Cut a section of the structure and visualized the load path	V	Own

Structural element was unstable	Did not consider load path for all loading conditions	Visualized the load path	V	Other
Structural system was not stable	Site conditions changed such that a column was no longer viable and was removed, but the structural system was not updated	Visualized the load path	V	Other
Member underdesigned	Error in in-house software	Beam depth was outrageously small	X	Other
Member underdesigned	Input loads were in units different from what the computer software was assuming	Calculated deflection was outrageously large	X	Own
Foundation was too small	Failed to account for overturning moment; just considered gravity loads	Footing that must resist overturning was approximately the size of the supported column	X	Other

297

298 **Note:**

299 *Categories of Tools*

300 C = Comparison (calculation based)

301 F = Field

302 I = Information Check (no calculations)

303 NR = Not Reported

304 O = Other

305 P = Previous Experience

306 R = Rule of Thumb

307 V = Visualization (of load path)

308 X = Extreme Value

309

310 **Table 5.** Examples of tools for finding errors in analysis and design results not linked to a specific
311 instance of error detection.

312

What is unreasonable [The Problem]	What happens to bring about the problem [The Error]	How to know there was a problem [Tool for Evaluating]	Category of Tool
Computer model does not represent the intended behavior	Loading, supports, member properties, and/or connectivity are not what thought	Check that the deflected shape is what expect	C
	Loading in computer model is not what thought	Compare the base shear calculated by hand with the total shear calculated by computer	C
		Compare the base shear of the computer model with the applied load	C
	Accidentally fix a node in the computer model that should not be restrained	Compare the base shear of computer model with the applied load	C
		Compare the base shear of computer model with the applied load	C
		Compare the brace force from computer model with a hand calculated force	C

Incorrect building response	Assigning incorrect mass density in the computer model	Compare the computer calculated period of vibration with the code approximation	C
		Compare the computer calculated period of vibration with the code approximation	C
Members oversized	Accidentally setting the deflection limit to a fixed amount for all beams regardless of length	Compare the computer selected beams with hand calculated designs	C
		Compare the computer selected gravity columns with hand calculated designs	C
Members under- or oversized	Inappropriate assumptions are made in software program	Compare new software programs to programs that have produced acceptable results	C
	Assumptions of a computer program are not consistent with those made by the designer	Compare the results from two different computer programs	C
Exterior columns are larger than interior columns		Compare the sizes of perimeter columns to interior columns	C
		Compare the total weight of the structure with column reactions in the computer model	C
	Loading in the computer model is not what the designer thought	Compare the weight of the building with the total axial load calculated by the computer	C

Members underdesigned		Drift of the braced frame exceeds its drift limit	C
	Loading, supports, member properties, and/or connectivity in the computer model are not what the designer thought	For dynamic analysis, draw a diagram of force at levels and compare the anticipated behavior with the computer predicted behavior	C
Incorrect building response		For new situations, model the structure in three to four different ways: at least two by hand and one or two numerically	C
Computer model does not represent the intended behavior	Loading in the computer model is not what the designer thought, possibly due to inconsistent units; supports are provided in locations not intended	Reactions do not add up to the load applied to the structure	C
Deformation of the structure under self-weight interferes with erection	Designing for minimum weight without regard to constructability	Pieces do not fit in the field	F
	Loading in the computer model is not what thought	Check the magnitude and location of the applied loads in the computer analysis	I
Insufficient details are drawn	Failing to recognize that a single detail is being referenced for multiple, different conditions	Review the design drawings for sufficient information	I
Support conditions are not consistent with the assumed conditions for analysis	Drawing details are either not provided or will not behave in the manner assumed for analysis	Review the design procedure	I

Beams and connections in a braced frame are not designed for axial force	Computer analysis assumes a rigid diaphragm, so the horizontal component of the brace force transfers through the diaphragm rather than the beam	Check for the specific problem since common	O
Underdesign the foundation below a chevron frame	Designing based on column axial, thus forgetting the contribution from the brace	Check for the specific problem since common	O
Foundations are inadequate for uplift	Failing to consider foundation capacity when designing the structural system	Check structure overturning	O
Excessive cracking of slab	Failing to identify the `effect of different supporting beam deflections on the slab	Review the design procedure	O
Members oversized		Compare pounds of structural steel per square foot of structure with average values for the type and size of structure	P
		Member size not is typical for the span and loading conditions based on experience	P
Computer indicates that members are understrength when actually fine	New version of computer software has errors	Previous experience can identify the issue	P
Connection unnecessarily difficult to fabricate or erect	Lack of understanding of fabrication or erection processes	Previous experience can identify the issue	P

Member underdesigned		Relative scale of the column to the beam looks odd based on previous experience	P
Inadequate anchorage of diaphragms to lateral elements	Designer misses part of the load path	Cut a section of structure and visualize the load path	V
Column stops at a level without transferring to other columns		Visualize the load path	V
Members underdesigned	Specifying that the deck runs parallel to the beams	All computer selected filler beams are W8x10	X

313

314 **Note:**

315 *Categories of Tools*

316 C = Comparison (calculation based)

317 F = Field

318 I = Information Check (no calculations)

319 O = Other

320 P = Previous Experience

321 V = Visualization (of load path)

322 X = Extreme Value

323

324

325 **Table 6.** Examples of common errors, the problem that typically results, and possible categories
 326 of tools for identifying the presence of the errors.

327

What is unreasonable [The Problem]	What happens to bring about the problem [The Error]	Possible Category of Tool
Beams underdesigned	Analysis performed in 3D with rigid diaphragm which slaves the nodes, so no axial forces are produced	C
Incorrect building response	Incorrectly modelling the idealized structure	C
Incorrect building response	Incorrectly orienting members in the numerical simulation	C
Member underdesigned	Analysis is in one set of units, but assuming another when selecting members	C
Member underdesigned	Not recognizing the difference between torsion in plane and torsion out of plane when reviewing computer results	C
Member underdesigned	Forgetting to convert mass to weight when working in metric units	C
Member underdesigned	Using feet instead of inches in a computer model	C
Members under- or oversized	Computer program does not perform as intended when buttons used out of order	C
Members under- or oversized	Failing to check the validity of computer program default values	C
Members under- or oversized	Inputting material density in units different from what the computer software is assuming	C
Members under- or oversized	Software being used for a situation for which it is not intended	C

Members under- or oversized	Using a computer program in situations for which it is not designed, but the manual does not indicate the limitation	C
Inadequate loads used for design	Lack of understanding of how to use the pertinent codes	I
Incorrect member size	Numbers being transposed during drafting	I
Insufficient information on drawings	Failing to consider what information would be required for fabrication and/or construction	I
Insufficient information on drawings	Failing to consider what information would be required for fabrication and/or construction	I
Members or connections underdesigned	Failing to use the correct code for that jurisdiction	I
Members underdesigned	Failing to recognize all the design criteria (e.g., road adjacent to retaining wall); failing to understand the project as a whole	I
Support conditions not consistent with assumed conditions for analysis	Drawing details are either not provided or will not behave in the manner assumed for analysis	I
Fabricator unable to complete the project from the drawings	Insufficient details drawn due to time constraints	O
Incorrect building response	Failing to incorporate the reduced stiffness of concrete members due to cracking	O
Incorrect dimensions on drawings	Using software incorrectly to calculate a dimension	O

Members underdesigned	Changes in loading are not articulated by the architect or are not noticed by the structural engineer	O
Members underdesigned	Changes in MEP are not noticed or anticipated by the structural engineer	O
Members underdesigned	Failing to consider pertinent earthquake information from the geotechnical report	O
Members underdesigned	Missing some loads from the architect's drawings	O
Reinforcement on wrong side of concrete member	Communication lacking between designer and draftsman	O
Structural layout does not match architectural and/or mechanical layout	Changes in layout are not articulated by the architect or not noticed by the structural engineer	O
Structural layout does not match architectural and/or mechanical layout	Changes in layout are not articulated by the architect or not noticed by the structural engineer	O
Structural layout does not match architectural layout	Changes in layout are not articulated by the architect or not noticed by the structural engineer	O
Concrete member detailed such that it is not easily constructed	Using design software that only ensures that the design meets code requirements	P
Concrete member detailed such that it is not easily constructed	Using design software to design members outside the range anticipated by the software	P

Connections not properly designed	Connectivity does not match the assumed behavior of the idealized structure used in the analysis	P
-----------------------------------	--	---

Connections or columns not properly designed	Failing to consider connection eccentricity	P
--	---	---

Incorrect column load takedown value	Not accounting for the effect of a cantilevered beam	P
--------------------------------------	--	---

Reinforcement does not have adequate development length	Failing to consider changes in beam depth along the length of a beam	P
---	--	---

Steel connection underdesigned	Failing to consider connection eccentricity	P
--------------------------------	---	---

328

329 **Note:**

330 *Categories of Tools*

331 C = Comparison (calculation based)

332 I = Information Check (no calculations)

333 O = Other

334 P = Previous Experience

335